


FIG. 17



F I G. 3




FIG. 18




FIG. 4a

FIG. 1




FIG. 19





FIG. 20




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 40




FIG. 41




FIG. 8




FIG. 13




FIG. 14




FIG. 15




FIG. 11




FIG. 12





FIG. 16






FIG. 21




FIG. 22




FIG. 23




FIG. 24




FIG. 25




FIG. 26




FIG. 27




FIG. 28




FIG. 29




FIG. 30




FIG. 31




FIG. 33




FIG. 32




FIG. 26a




FIG. 26b




FIG. 26c




FIG. 26f




FIG. 26d





FIG. 26e






FIG. 34




FIG. 35





FIG. 36




FIG. 37




FIG. 38




FIG. 39

7/21






FIG. 45





FIG. 46





FIG. 47

FIG. 48





9/21

FIG. 49




FIG. 50




FIG. 52




FIG. 51




FIG. 53




FIG. 54




FIG. 55




FIG. 56




FIG. 57




FIG. 58




FIG. 59




FIG. 61





FIG. 60

FIG. 62




FIG. 63




FIG. 64




FIG. 65




FIG. 66





FIG. 67

FIG. 68




FIG. 69




FIG. 71




FIG. 70





FIG. 72






FIG. 70a




FIG. 70b




FIG. 70c




FIG. 70d






FIG. 73




FIG. 74




FIG. 75




FIG. 76




FIG. 77a




FIG. 77




FIG. 78




FIG. 79




FIG. 80




FIG. 81




FIG. 82




FIG. 83




FIG. 84






FIG. 85




FIG. 86




FIG. 87




FIG. 88




FIG. 89




FIG. 90




FIG. 91




FIG. 92





FIG. 93





APPROVED O.G. FIG.  
CLASS SUBCLASS  
DRAFTSMAN

20/21

FIG. 94a




FIG. 94b




FIG. 95




FIG. 96




FIG. 97





FIG. 98



+

FIG. 99





FIG. 100



+